



Federal Aviation Administration

SAFETY ALERT

Date: April 19, 2013

To: Users of the Terminal Procedures Publication North Central Volume 3 (NC-3) and Users of the digital - Terminal Procedures Publication (d-TPP) DVD.

From: Aeronautical Navigation Products (AeroNav Products)

Subject: Correction to the TPP NC-3 and the d-TPP DVD for the May 2, 2013 Effective Date for Kansas City Intl Airport, Kansas City, MO (MCI).

The 2 May 2013 Terminal Procedures Publication (TPP) North Central Volume 3 (NC-3) and the digital-Terminal Procedures Publication (d-TPP) DVD Volume 1305 contain two incorrect charts at Kansas City Intl. Airport, Kansas City, MO, (MCI).

The following charts in the bound (TPP) North Central Volume 3 (NC-3) dated May 2, 2013, are incorrect and should not be used:

Kansas City Intl (MCI), ILS RWY 19R (CAT II & III), Amdt 10B
Kansas City Intl (MCI) ILS RWY 01R (CAT II & III), Amdt 4

To obtain the corrected charts, you can download them from the AeroNav website at: http://aeronav.faa.gov/d-tpp/1305/00780I1RC2_3.PDF
http://aeronav.faa.gov/d-tpp/1305/00780I19RC2_3.PDF

PLEASE NOTE: No "patch" for the 1305 d-TPP DVD is being provided. If you access d-TPP by running the DVD, the corrected files will not automatically be added. However, if you installed the d-TPP onto your computer, the corrected files can be downloaded from the AeroNav website and copied into the "published pdfs" your folder of d-TPP copy and the program will access them normally.

For technical assistance, please call 1 (800) 626-3677 or e-mail:
[9-AMC- Aerochart@FAA.gov](mailto:9-AMC-Aerochart@FAA.gov)