

NOTICE

U.S. Department of Transportation
Federal Aviation Administration

N 8200.92

06/20/06

Cancellation
Date: 06/20/07

SUBJ: Interim Change to FAA Order 8200.1C, Chapter 11, Rho and Theta Systems

- 1. PURPOSE.** This Notice is being issued as interim guidance to FAA Order 8200.1C, United States Standard Flight Inspection Manual, Chapter 11, Rho and Theta Systems checklist.
- 2. DISTRIBUTION.** This Notice is distributed to Air Traffic Technical Operations Service Areas, to the Air Force Flight Standards Agency, to the U.S. Navy Airspace and Air Traffic Control Program, to the U.S. Army Air Traffic Control Center, to all Aviation System Standards Flight Inspection Operations Offices and Crewmembers, and to special addressees.
- 3. BACKGROUND.** FAA Order 8200.1C, dated October 2005, did not carry forward the requirement to revalidate Expanded Service Volumes (ESVs) when a coverage orbit is accomplished for Rho Theta facilities. This was an oversight and will be included in the next update of FAA Order 8200.1.
- 4. GUIDANCE:** Add the following to Order 8200.1C, Chapter 11, Paragraph 11.12 Checklist:
 - a.** Footnote 13. ESV(s) must be revalidated any time a coverage orbit is accomplished.
 - b.** In the CHECK column, Orbits Coverage block, add “**(13)**” to denote the application of Footnote 13.

/s/

Thomas C. Accardi
Director of Aviation System Standards

Distribution: ATO-W Service Areas; **Initiated By:** Air Traffic Technical Operations (ATO-W)
Air Force Flight Standards Agency; Aviation System Standards
U.S. Navy Airspace and ATC Program; Flight Inspection Policy (AJW-331)
U.S. Army ATC Center; Aviation System Standards
Flight Inspection Operations Offices and Crewmembers